


1288122 - R8 SDMS

80th Avenue Tank Farm - PCB results

Jennifer.Laggan

to:

Mike Zimmerman

03/21/2011 01:37 PM

Cc:

GLHONEYM, RBeierle, Hoyt.Sutphin, RSHANASH

Hide Details

From: <Jennifer.Laggan@CH2M.com>

To: Mike Zimmerman/R8/USEPA/US@EPA

Cc: <GLHONEYM@up.com>, <RBeierle@cdphe.state.co.us>,
<Hoyt.Sutphin@CH2M.com>, <RSHANASH@UP.COM>

History: This message has been forwarded.

2 Attachments



1103600 Commerce City CO - UPRR Results.pdf 1102433 Commerce City CO - UPRR Final.pdf

Mike:

Attached are the preliminary results from the PCB analyses on tanks A101 and 10010. A review of these results indicates that PCBs were reported as Not Detected below the 50 ppm threshold for regulation under TSCA.

I have also attached the final TCLP results for these two tanks. Specifically, this reports amend the original report to include the results of the TCLP VOC and SVOC analysis for tank A101. A review of these results and the PCB results mentioned above indicates that the material is not hazardous.

Based on these findings UPRR intends to pursue fuel recovery for disposition of the contents of these two tanks.

Please contact me at your earliest convenience to discuss.

Thanks,

Jen

Jennifer P. Laggan, P.G.
CH2M Hill
9191 South Jamaica Street
Englewood, CO 80112-5946
Office 720.286.0513
Mobile 303.249.4273
Fax 720.286.8135